




RAT Observation

- No Observed Source Material (3)
- Possible Source Material (0)
- Source Material Observed (0)





T175-1 RES - KARLBERG THOMAS L - 36037 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 537204 | 4/29/2025 9:12:17 AM
(40.522633, -104.601957)
No visible product no odor





T175-1 RES - KARLBERG THOMAS L - 36037 CR 49 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 537230 | 4/29/2025 9:16:53 AM
(40.522732, -104.601921)

No visible oil staining on topsoil or vegetation. Location south of house on property east of garage.



Oiling Observation: 0 No Observable Oil | Id: 537253 | 4/29/2025 9:28:05 AM

(40.52444, -104.601739)

Pipe fence on far end of property.

No hydrocarbons detected.



Oiling Observation: 0 No Observable Oil | Id: 537242 | 4/29/2025 9:33:41 AM
(40.522643, -104.60195)
Main residence

No hydrocarbons detected.

