



RAT Observation

- No Observed Source Material (19)
- Possible Source Material (0)
- Source Material Observed (0)

Observation

Oiling Observation: **0 No Observable Oil** | Id: 538834 | 4/30/2025 11:10:39 AM
(40.508425, -104.602381)
No obvious presence of hydrocarbons on John Deere tractor





T150 AG - SCHELLER MICHAEL - 35071 COUNTY ROAD 49
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 538832 | 4/30/2025 11:17:46 AM
(40.508182, -104.602914)
No obvious presence of hydrocarbons on front and loader



Oiling Observation: 0 No Observable Oil | Id: 538837 | 4/30/2025 11:19:02 AM
(40.507995, -104.602053)
No obvious presence of hydrocarbons on trailer. Trailer number 7-784.





T150 AG - SCHELLER MICHAEL - 35071 COUNTY ROAD 49
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 538860 | 4/30/2025 11:21:00 AM
(40.508073, -104.601734)

Soil and vegetation all appear to have normal coloration. No coloration on the sorbent pad when wiped on vegetation. No signs of residue observed.





T150 AG - SCHELLER MICHAEL - 35071 COUNTY ROAD 49
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 539079 | 4/30/2025 11:22:01 AM
(40.507839, -104.601948)

No presence of impacted material found at location.





T150 AG - SCHELLER MICHAEL - 35071 COUNTY ROAD 49
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 538858 | 4/30/2025 11:23:00 AM
(40.50817, -104.601926)

Soil, vegetation, and metal posts all appear to have normal coloration. No coloration on the sorbent pad when wiped on vegetation or metal posts. No signs of residue observed.



Oiling Observation: 0 No Observable Oil | Id: 538835 | 4/30/2025 11:23:13 AM
(40.508404, -104.602674)
No obvious impact of hydrocarbons on items south side of shed





T150 AG - SCHELLER MICHAEL - 35071 COUNTY ROAD 49
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 539081 | 4/30/2025 11:24:17 AM
(40.507815, -104.602249)
No presence of impacted material found at location.





T150 AG - SCHELLER MICHAEL - 35071 COUNTY ROAD 49
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 539097 | 4/30/2025 11:29:00 AM
(40.507785, -104.603223)
No presence of impacted material found at location.



Oiling Observation: 0 No Observable Oil | Id: 538861 | 4/30/2025 11:33:00 AM
(40.508202, -104.602631)

Soil, and vegetation all appear to have normal coloration. No coloration on the sorbent pad when wiped on vegetation. No signs of residue observed.

