

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404267848

Date Received:

07/03/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 717100233

Inspection Date: 05/21/2025

FIR Submit Date: 06/10/2025

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: SENE Sec: 36 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.096158 Longitude: -104.945565

FACILITY - API Number: 05-123-

-00

Facility ID: 483070

Facility Name: State 14

Number: _____

Qtrqtr: SENE Sec: 36 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.096158 Longitude: -104.945565

CORRECTIVE ACTIONS:

1 CA# 205464

Corrective Action: Comply with ECMC Rules. Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a. Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR. Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules.

Date: 07/10/2025

Response: CA COMPLETED

Date of Completion: 07/03/2025

Stained soil have been cleaned up and removed around wellhead. Issue has been fixed: stuffing box was tightened. Please see attached pictures.

Operator _____
Comment: _____

ECMC Decision: _____

ECMC Representative: _____

2 CA# 205465

Corrective Action: Comply with Rule 606. Date: 06/17/2025

Response: CA COMPLETED Date of Completion: 06/17/2025

Operator Comment: All weeds have been removed around location including electrical equipment. Please see attached pictures.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 205467

Corrective Action: Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil. Date: _____

Response: CA COMPLETED Date of Completion: 06/27/2025

Operator Comment: Stockpile has been removed from location. Please see attached pictures.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili Signed: _____

Title: RC Engineer Date: 7/3/2025 2:22:19 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404267902	Stained soil removed PIC1
404267907	Stained soil, weeds, stockpile removed PIC2

Total Attach: 2 Files