

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad
Location ID: 335136



**Location Overview: Location is within High Priority/Density
Habitat areas. Location is approximately 207 yards from
creek/drainage that contributes to the Colorado River.
Section/Township/Range: 20 6S94W**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad
Location ID: 335136



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.