

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2025

Submitted Date:

07/11/2025

Document Number:

719000309**FIELD INSPECTION FORM**Loc ID 325533 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 6300 S SYRACUSE WAY, SUITE 525City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Klye		kwalter@enduringresources.com	SJB inspections

General Comment:

Inspection Report Summary
 On 7/11/25 I Inspector Charles Garcia
 conducted an on-site FOLLOW UP inspection.DOCUMENT #719000115 FIR DOCUMENT#404253627
 Location: STATE-ROYCE 1-36
 Operator:ENDURING RESOURCES
 API#: 067-06564
 County: LaPlata

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					

Comment: Stormwater management sediment and erosion control
CHECK DAMS FULL OF SEDIMENT ON EAST SIDE OF LOCATION CAUSING
EROSION ADDITIONAL BMP'S MAY BE NEEDED
CA HAS BEEN RESOLVED SEE LOCATION PICTURES

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
CA RESOLVED FIR DOCUMENT #404253627	garciacr1	07/11/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000310	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138833