

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404153521

Date Received:

07/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Popejoy, Dusty

dusty.popejoy@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303440

Inspection Date: 02/11/2025

FIR Submit Date: 02/12/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335394

Location Name: PUCKETT-66S96W Number: 32SWNW County: _____

Qtrqr: SWN Sec: 32 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.483118 Longitude: -108.138667

FACILITY - API Number: 05-045-00 Facility ID: 335394

Facility Name: PUCKETT-66S96W Number: 32SWNW

Qtrqr: SWN Sec: 32 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.483118 Longitude: -108.138667

CORRECTIVE ACTIONS:

1 CA# 202522

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/28/2025

Response: CA COMPLETED

Date of Completion: 04/01/2025

Operator Comment:	Ditches have been cleaned and road has been bladed/graded. The sediment that encroached production equipment has been removed. Corrective Action complete.
ECMC Decision:	
ECMC Representative:	

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	Ditches have been cleaned and road has been bladed/graded. The sediment that encroached production equipment has been removed. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 7/21/2025 9:52:05 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404153521	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files