

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404155642

Date Received:
07/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com
Popejoy, Dusty		dusty.popejoy@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303552
Inspection Date: 03/05/2025 FIR Submit Date: 03/10/2025 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324117

Location Name: UNOCAL-66S96W Number: 33NESW County:
Qtrqtr: NESW Sec: 33 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.478368 Longitude: -108.115647

FACILITY - API Number: 05-045- -00 Facility ID: 324117

Facility Name: UNOCAL-66S96W Number: 33NESW
Qtrqtr: NESW Sec: 33 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.478368 Longitude: -108.115647

CORRECTIVE ACTIONS:

1 CA# 203162

Corrective Action: Repair wildlife netting to prevent wildlife entry. Date: 03/18/2025

Response: CA COMPLETED Date of Completion: 04/01/2025

Operator Comment: Netting has been repaired. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

2 CA# 203163

Corrective Action: Remove unused/stored equipment.

Date: 03/18/2025

Response: CA COMPLETED

Date of Completion: 04/01/2025

Operator
Comment: Equipment has been removed. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

3 CA# 203164

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/25/2025

Response: CA COMPLETED

Date of Completion: 04/01/2025

Operator
Comment: Stormwater BMP's have been refreshed for proper stormwater diversion. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #203162: Netting has been repaired. Corrective Action complete.
CA #203163: Equipment has been removed. Corrective Action complete.
CA #203164: Stormwater BMP's have been refreshed for proper stormwater diversion. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 7/21/2025 12:43:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404155642	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files