

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404155951

Date Received:  
07/21/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>
<u>Popejoy, Dusty</u>		<u>dusty.popejoy@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303544  
Inspection Date: 03/05/2025 FIR Submit Date: 03/07/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334932

Location Name: AMERICAN SODA-67S96W Number: 2SWSE County: \_\_\_\_\_  
Qtrqtr: SWSE Sec: 2 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.462449 Longitude: -108.073195

FACILITY - API Number: 05-045- -00 Facility ID: 334932

Facility Name: AMERICAN SODA-67S96W Number: 2SWSE  
Qtrqtr: SWSE Sec: 2 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.462449 Longitude: -108.073195

CORRECTIVE ACTIONS:

**1** CA# 203106

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/16/2025

Response: CA COMPLETED Date of Completion: 03/24/2025

Location and access road have been bladed/graded to remove rill and increase stabilization. Corrective Action complete.

Operator \_\_\_\_\_  
Comment: \_\_\_\_\_

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: Location and access road have been bladed/graded to remove rill and increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith Signed: \_\_\_\_\_

Title: TEP Representative Date: 7/21/2025 1:11:13 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files