

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2025

Submitted Date:

07/23/2025

Document Number:

712300161

FIELD INSPECTION FORM

Loc ID: 324749 Inspector Name: Maxwell, Logan On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		aaron.trujillo@state.co.us	
		wes.corliss@fulcrumeo.com	
		annalee@fulcrumef.com	
		inspections@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290930	WELL	PA	11/15/2018	GW	057-06463	BUFFALO DITCH 1-32H	RI
324749	LOCATION	AC			-	BUFFALO DITCH-67N80W 32SENE	RI
463858	OFF-LOCATION FLOWLINE	AC	04/11/2019		-	Production Line 32SENE	RI

General Comment:

On 06/05/2025, Northwest Reclamation Specialist Maxwell, conducted a final reclamation inspection at Fulcrum Energy Operating's Buffalo Ditch 1-32H Oil and Gas Location in Jackson County, Colorado.

The Form 6S (# 401755764) was approved for abandonment 11/15/2018.

The Location is in the following HPH: Black bear and 1202.d. density Greater Sage-grouse Priority Habitat Management.

The following compliance issues were observed during this inspection:

- Weedy Debris
- Final Reclamation
- Flowline abandonment

Refer to the Location and Reclamation sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective actions from previous inspections that have not been addressed remain applicable. Any new corrective actions without corrective action dates, requires that the Operator comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Fencing remains around the pad Location. Upon closure of the Location, fencing shall be removed per Rule 1004.		
Corrective Action:		Date:	

Equipment:

Type: Flow Line	#		corrective date
Comment:	It was observed that flowlines have not been properly abandoned in the COGIS database and remain as an "active" status.		
Corrective Action:	Rule 1105.f.- Properly abandon flowlines.		Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 290930 Type: WELL API Number: 057-06463 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324749 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463858 Type: OFF- API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

It was observed in this inspection that Final Reclamation of the Location is not complete in accordance with 1004 requirements. Gravel/road base has not been removed from the Location; compaction issues remain apparent. Evidence of undesirable plant species (e.g., Russian Thistle) observed.

Previous revegetation efforts are evident, however plant germination and establishment is unsuccessful. It appears that compaction may be hindering plant growth.

Corrective Action: **Comply with Rules 1004.a., 1004.d., and 606.**

Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, no stormwater issues were observed.

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712300163	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7161481