

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/23/2025
Submitted Date:
07/25/2025
Document Number:
711902647

FIELD INSPECTION FORM

Loc ID 313811 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:
13 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------------|---------|
| Fritzler, Gene | | gfritzler@firesources.com | |
| Heibel, Krystal | | krystal.heibel@state.co.us | |
| Quint, Craig | | craig.quint@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 225296 | WELL | PR | 02/01/2025 | OW | 087-05698 | MENKE 4 | PR |

General Comment:

SNAPSHOT FIR 2025 - CA'S ARE CITED WITHIN THIS FIR -
CONTACT ECMC ENVIRONMENTAL GROUP IMMEDIATELY FOR DIRECTIVES.
SEE ATTACHED PHOTOGRAPHS FOR COMPLIANCE REFERENCE

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | MAINTAIN LEASE ROAD | | |
| Corrective ActionL | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | COMPLY WITH RULE 605 SERIES | Date: | 10/23/2025 |
| Type | WELLHEAD | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | REMOVE TRASH - DEBRIS FROM AREA/LOCATION | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| Crude Oil | | | |
| Comment: | CONTACT ECMC ENVIRONMENTAL GROUP WITHIN (48) HOURS OF NOTIFICATION SEE ATTACHED PHOTOS - PREVIOUS SPILL OR TANK BOTTOMS INCORPORATED WITHIN SOILS AT BERMS AND PAD FLOOR. REMOVE/REMEDiate SOILS PER ECMC ENVIRONMENTAL GROUP DIRECTIVES. | | |
| Corrective Action: | COMPLY WITH RULE 906 AND 912 SERIES | | Date: 07/28/2025 |
| Lube Oil | Pump Jack | | |
| Comment: | REPAIR GEAR BOX LEAK CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES SEE ATTACHED PHOTOS | | |
| Corrective Action: | COMPLY WITH RULE 906 & 912 SERIES | | Date: 07/28/2025 |
| In Containment: Yes | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Other | # 0 | | corrective date |
| Comment: | NO CHANGE IN EQUIPMENT INVENTORIED | | |
| Corrective Action: | | Date: | |

| Tanks and Berms: | | | | | | |
|-------------------------|----------|--|---------------------|-------------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| | | | | | | |
| Comment: | | NO CHANGE IN TANK CONFIGURATION | | | | |
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: | | CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES WITHIN (48) HOURS OF NOTIFICATION SOILS AFFECTED BY PREVIOUS SPILLS OR TANK BOTTOMS INCORPORATED WITHIN BERMS AND INSIDE BERMS ON PRODUCTION FLOOR. | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Inspected Facilities

Facility ID: 225296 Type: WELL API Number: 087-05698 Status: PR Insp. Status: PR

Producing Well

Comment: OW
CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES WITHIN (8) HOURS
OF NOTIFICATION

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: TANK BOTTOMS

Estimated Spill Volume: _____

Comment: OIL SATURATED MATERIAL INCORPORATED WITHIN BERMS AND ON PRODUCTION FLOORCONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES WITHIN (48) HOURS OF NOTIFICATION

Corrective Action: COMPLY WITH RULE 905, 906 & 912 SERIES. CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES WITHIN (48) HOURS OF THIS NOTIFICATION

Date: 07/28/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| SNAPSHOT FIR 2025 CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES WITHIN (48) HOURS OF THIS NOTIFICATION | schureky | 07/25/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 711902653 | PHOTOGRAPHS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7161613 |