

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>07/10/2025</u> Submitted Date: <u>07/26/2025</u> Document Number: <u>698603823</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 336870 Inspector Name: St John, William (Cal) On-Site Inspection   
 2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 66190  
 Name of Operator: OMIMEX PETROLEUM INC  
 Address: 100 CRESCENT CT SUITE700-#5528  
 City: DALLAS State: TX Zip: 75201

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Abrahms, Deborah		deborah.abrams@state.co.us	OWP
Reinhardt, Kelley		kelley.reinhardt@state.co.us	OWP
Hickey, Mike		michael.hickey@state.co.us	OWP

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280170	WELL	SI	06/01/2022	GW	125-09517	BENNETT STATE 1-16-5-45 (OWP)	SI

**General Comment:**

On 7/10/2025 inspector completed site investigations on the Bennett wells located in the 5N46W section previously operated by the now defunct operator Omimex Petroleum Inc. The wells previously operated by Omimex have been moved into the State's Orphaned Well Program. I received a complaint from a non-land owner local resident who had come across the leaking well during farming operations. He stated the gas could be smelled and heard at the location. Complainant called the phone number posted at the well site to report it but stated the call would not go through and didn't want to call 911. He didn't know what else to do so he went back to work and avoided the area. In our conversation he could only provide me with a vague well location and only remember the name Bennett being on the well sign. He provided me with a County Road number that allowed me to narrow the search area down. The inspector recommends that additional emergency contact signage be placed at the orphaned wells and production facilities with ECMC's contact/Complaint information to allow timely reporting by the general public. In this specific case the Omimex contact phone number has no disconnect message or cannot be completed as dialed message associated with it. It simply appears to go through and then hangs up.

Previous ECMC inspections on Omimex Petroleum Inc. wells identifying their lack of routine maintenance and disregard for best maintenance practices at their locations prior to their shut down has led to the identification of numerous wells now in the State of Colorado's receivership as a potential danger/hazard to public safety, Welfare, the environment and wildlife resources. The Orphaned Well Program is aware of many of these well issues and has completed two phases of emergency well plugging projects specifically on the Omimex wells and is currently working on a third emergency plugging package pending approval. This well will be added to the growing list of problem wells that require P&A.

See previous inspection completed 08/10/2023 Document number 698600925 for additional details of location inventory and 9 corrective actions identified to Operator.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Old Operator Lease sign at wellhead location.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Old Operator Lease sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Old Operator Emergency contact information posted on Lease sign. No current contact information other than 911 posted.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds and vegetation growing at well location.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Post & Wire around surface equipment at remote gas metering location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed and tubing in the wellbore. Tubing valve not connected. Casing valve closed.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Remote Separator/Gas Meter Shed.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline riser at wellhead **Open ended**.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on Access at shared gathering location.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack Cement Pad.		
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead not plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Inspector could smell gas at the well location but could not determine source. Wind was blowing and soap mixture did not find any leaks at the well connections.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 280170 Type: WELL API Number: 125-09517 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603869	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7162365">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7162365</a>