

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2025

Submitted Date:

07/28/2025

Document Number:

711902428

FIELD INSPECTION FORM

Loc ID 317352 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Chris		smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262960	WELL	PR	04/26/2002	GW	121-10658	CHRISTIANSON-NIOBRARA 31-12	PR

General Comment:

ROUTINE FIR

Location			
Lease Road:			
Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	SATISFACTORY		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	NONE		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 0		corrective date
Comment:	NO CHANGE		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 262960 Type: WELL API Number: 121-10658 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ROUTINE FIR SATISFACTORY	schureky	07/28/2025