



STATE OF COLORADO
OIL GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

RECEIVED

JAN 23 1990

SUBMIT ORIGINAL AND 1 COPY

FOR OFFICE USE ONLY

ET	FE	UC	SE
----	----	----	----

5. FEDERAL INDIAN OR STATE LEASE NO.

SUNDRY NOTICES AND REPORTS ON WELLS *COLO. OIL & GAS CONS. COMM.*

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL COALBED METHANE INJECTION WELL OTHER

2. NAME OF OPERATOR: Benson Mineral Group, Inc.

3. ADDRESS OF OPERATOR: 1536 Cole Blvd, Suite 220
CITY STATE ZIP CODE
Golden, CO 80401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface: 1700' ENL & 2040' FEL
At proposed prod. zone

5. FEDERAL INDIAN OR STATE LEASE NO.

6. PERMIT NO. 82-1156

7. API NO. 05001 8174

8. WELL NAME TUPPS 00554

9. WELL NUMBER 4-32

10. FIELD OR WILDCAT BEAR Gulch

11. QTR. QTR. SEC., T.R. AND MERIDIAN 5 W NE SEC. 4 - T35-R64W

12. COUNTY Adams

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER _____

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- REPAIRED WELL
- OTHER _____

*Use Form 5 - Well Completion or Recompletion Report and Log for subsequent report of Multiple/Commingled Completions and Recompletions

13C. NOTIFICATION OF:

- SHUT-IN/TEMPORARILY ABANDONED (DATE _____) (REQUIRED EVERY 6 MONTHS)
- PRODUCTION RESUMED (DATE _____)
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK 11/4/89

Set a CIBF @ 8,020 and 4 sacks of cement.
Loaded the hole, and cut casing at 4,550'.
Laid down the casing and ran in with tubing to 1660'
Spotted 50 sacks of cement at 1,660'. Laid down tubing to 1,390'.
Spotted 50 sacks of cement at 1,390'. Laid down tubing to 470'.
Spotted 50 sacks of cement at 470'. Laid down tubing to 239',
219' is the base of surface.
Set 35 sacks of cement 1/2 in and 1/2 out of surface.
Set 5 sacks at surface.
Cut the wellhead off 4' down, and welded a plate.
Backfilled the hole, and dug the deadmen.

16. I hereby certify that the foregoing is true and correct

SIGNED Raymond G. Nance TELEPHONE NO. (303)232-0100

NAME (PRINT) Raymond G. Nance TITLE Prod. Dept. DATE January 22, 1990

(This space for Federal or State office use)

APPROVED M. Jewell TITLE _____ DATE 2/11/90

CONDITIONS OF APPROVAL, IF ANY: