

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 42-14 Pad

Location ID: 334735



Photo # 5233 From entrance to location



Photo # 5234 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 42-14 Pad

Location ID: 334735



Photo # 5235 Location



Photo # 5236 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 42-14 Pad

Location ID: 334735



Photo # 5237 Location



Photo # 5238 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 42-14 Pad

Location ID: 334735



Photo # 5239 Location



Photo # 5240 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 42-14 Pad

Location ID: 334735



Photo # 5241 Improperly marked deadman



Photo # 5242 Same improperly marked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 42-14 Pad

Location ID: 334735



Photo # 5243 Unmarked deadman



Photo # 5244 Same unmarked deadman