

State of Colorado
Energy & Carbon Management Commission



Document Number:
404304584

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
08/04/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10670
Name of Operator: BISON IV OPERATING LLC
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Paul Buck	303-882-5868	pbuck@bisonog.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696307867
Inspection Date: 07/29/2025 FIR Submit Date: 07/29/2025 FIR Status: _____

Inspected Operator Information:

Company Name: BISON IV OPERATING LLC Company Number: 10670
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 416477

Location Name: Fox Creek Number: 505-2501H County: _____
Qtrqtr: SESE Sec: 25 Twp: 12N Range: 63W Meridian: 6
Latitude: _____ Longitude: _____

FACILITY - API Number: 05-123-00 Facility ID: 481563

Facility Name: Fox Creek 505-2501H Tank Battery Number: _____
Qtrqtr: SESE Sec: 25 Twp: 12N Range: 63W Meridian: 6
Latitude: _____ Longitude: _____

CORRECTIVE ACTIONS:

1 CA# 206532

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Date: 08/12/2025

Response: CA COMPLETED Date of Completion: 08/01/2025

Operator Comment: The stained soils around the loadout buckets and the north tank have been removed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 206533

Corrective Action: Comply with Rule 606

Date: 08/12/2025

Response: CA COMPLETED

Date of Completion: 08/01/2025

Operator
Comment: All unused equipment in the berm has been removed.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions for stained soil and oil waste, and for unused equipment on site have been performed. Pictures of corrective actions are attached. Bison is unable to attach photographic evidence of the corrective actions and will email them to the inspector directly.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Buck

Signed: _____

Title: EH&S Manager

Date: 8/4/2025 2:35:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files