

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2025

Submitted Date:

08/04/2025

Document Number:

707801734

FIELD INSPECTION FORM

 Loc ID 312780 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 45898
 Name of Operator: KAISER-FRANCIS OIL COMPANY
 Address: P O BOX 21468
 City: TULSA State: OK Zip: 74121
Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Opfer, Christina	(918) 491-4468	christinao@kfoc.net	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222380	WELL	PR	01/01/2024	GW	081-05372	FOX GOV 1-30	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection/ audit on site at Kaiser Francis Fox Gov 1-30, at Location # 312780 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Random debris
2. Belt guard missing
3. Well signage is lacking information.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Well head lacks information		
Corrective Action:	Within 60 days after a new Well is Completed, including each Well on a Multi-Well Site, or an existing sign is replaced or modified, a permanent sign will be conspicuously located at the wellhead and will identify: A. The Well name; B. The API number; and C. Its legal location, including the quarter/quarter section. When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: A. Name of the Operator; B. Telephone number at which the Operator can be reached at all times; C. Telephone number for local emergency services (911 where available); and D. The public road used to access the Well.		Date: <u>09/04/2025</u>

Emergency Contact Number:			
Comment:	<u>(405) 262-5511</u>		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris		Date: <u>08/22/2025</u>
Type	OTHER		
Comment:	Belt guard missing on pump jack		
Corrective Action:	Eliminate possibility of wildlife or personnel from being harmed from equipment.		Date: <u>08/22/2025</u>

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	500 gallon methanol tank in metal containment		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 222380 Type: WELL API Number: 081-05372 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801738	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174081