

Topaz Southwest, Inc.
Box 326
Shelbyville, TX 75973



RECEIVED

May 13, 1991

JUN 17 1991

COLO. OIL & GAS CONSV. COMM

SCANNED

Mr. Ed Binkley
Oil and Gas Conservation Commission, State of Colorado
1580 Logan Street, Suite 380
Denver, Colorado 80203

Dear Ed:

The OGCC Form 4 for the plugging of the Shadel No. 1 is enclosed along with a copy of the cement ticket and a copy of Jon Love's invoice for welding the cap.

Your taking the time to investigate and identify the old wells on the property was very much appreciated.

I located and posted a sign on the Baldwin No. 1 (it was further north than I had expected it to be and presented a much lower profile than any of Pecos Western's other wells).

I put up the signs on the all the wells Friday except for the Susie No. 1 and Sandoval No. 11. I had some trouble mounting these as a permanent fixture. Today, Jon Love's crew was scheduled to:

1. Replace the well head on the Susie No. 1
2. Install the signs at the Susie No. 1 and the Sandoval No. 11
3. Remove some cement from the Susie No. 1 location and and some debris at the Sandoval No. 7 location
4. Install a new valve on the Baldwin No. 1

Thanks again for your help.

Sandoval #11

Yours truly,


Ed Green
President