

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404311167

Date Received:
08/08/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10515
Name of Operator: GUNNISON ENERGY LLC
Address: 999 18TH STREET SUITE 1755N
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Chamard, Megan</u>		<u>megan.chamard@state.co.us</u>
<u>Gaasche, Emily</u>		<u>emily.gaasche@state.co.us</u>
.		<u>geops@oxbow.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100511
Inspection Date: 05/06/2025 FIR Submit Date: 05/08/2025 FIR Status:

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC Company Number: 10515
Address: 999 18TH STREET SUITE 1755N
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 427218

Location Name: DGU Federal 1289 Number: Section 18 Pad County:
Qtrqr: SWNE Sec: 18 Twp: 12S Range: 89W Meridian: 6
Latitude: 39.017192 Longitude: -107.378270

FACILITY - API Number: 05-051-00 Facility ID: 427218

Facility Name: DGU Federal 1289 Number: Section 18 Pad
Qtrqr: SWNE Sec: 18 Twp: 12S Range: 89W Meridian: 6
Latitude: 39.017192 Longitude: -107.378270

CORRECTIVE ACTIONS:

1 CA# 204676

Corrective Action: Install/maintain secondary containment BMP; ensure BMP is sufficiently impervious to contain a spill or release. Date:

Response: CA COMPLETED Date of Completion: 05/21/2025

See photo of Liner Repair completed 5/21/2025

Operator Comment: _____

ECMC Decision: _____

ECMC Representative: _____

2 CA# 204677

Corrective Action: In accordance with Rule 210.a- submit, attached to a Form 4, documentation of consultation with the Surface Owner regarding the seed mixture, and provide the seed tags of the "Surface Owner provided seed mixture" used during interim reclamation.

Date: 05/15/2025

Response: CA COMPLETED

Date of Completion: 05/15/2025

Operator Comment: All seed mixes used in accordance with Federal Guidelines and allowed under the Surface Use Agreement with Surface Owner.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: FIRR for Liner Repair performed 5/21/2025.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyson Johnston

Signed: _____

Title: Vice President Land

Date: 8/8/2025 5:57:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404311168	Photo1
404311169	Photo2

Total Attach: 2 Files