

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad
Location ID: 323862



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 10 7S96W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad
Location ID: 323862



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.