

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2025

Submitted Date:

08/04/2025

Document Number:

707801734

**FIELD INSPECTION FORM**

Loc ID 312780 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 45898  
 Name of Operator: KAISER-FRANCIS OIL COMPANY  
 Address: P O BOX 21468  
 City: TULSA State: OK Zip: 74121

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Opfer, Christina	(918) 491-4468	christinao@kfoc.net	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222380	WELL	PR	01/01/2024	GW	081-05372	FOX GOV 1-30	PR

**General Comment:**

[ECMC Inspection Report Summary](#)  
 On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection/ audit on site at Kaiser Francis Fox Gov 1-30, at Location # 312780 in Route county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.  
 During this inspection the following possible compliance issues were observed:  
 1. Random debris  
 2. Belt guard missing  
 3. Well signage is lacking information.

Refer to photograph of observed compliance issue.  
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well head lacks information		
Corrective Action:	<p>Within 60 days after a new Well is Completed, including each Well on a Multi-Well Site, or an existing sign is replaced or modified, a permanent sign will be conspicuously located at the wellhead and will identify:</p> <p>A. The Well name;                      B. The API number; and                      C. Its legal location, including the quarter/quarter section.                      When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign:                      A. Name of the Operator;                      B. Telephone number at which the Operator can be reached at all times;                      C. Telephone number for local emergency services (911 where available); and                      D. The public road used to access the Well.</p>	Date:	09/04/2025

Emergency Contact Number:		
Comment:	(405) 262-5511	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/22/2025
Type	OTHER		
Comment:	Belt guard missing on pump jack		
Corrective Action:	Eliminate possibility of wildlife or personnel from being harmed from equipment.	Date:	08/22/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank in metal containment		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222380 Type: WELL API Number: 081-05372 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404304922	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174090">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174090</a>
707801738	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174081">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174081</a>