

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2025

Submitted Date:

08/05/2025

Document Number:

713400953

**FIELD INSPECTION FORM**

Loc ID 314651 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 734 MAIN STREET 3RD FLOOR  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 14 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	
GAS, UTAH		inspections@utahgascorp.com	
Katz, Aaron		aaron.katz@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229197	WELL	PR	06/25/1961	GW	103-06284	DOUGLAS CREEK UNIT 7	PR

**General Comment:**

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign contains inaccurate nearest public road information Sign on meter house		
Corrective Action:	Comply with CECMC rule 605		Date: 09/05/2025
Type	WELLHEAD		
Comment:	Wellhead sign lacks required information		
Corrective Action:	Comply with CECMC rule 605		Date: 09/05/2025

<b>Emergency Contact Number:</b>		
Comment:	970-693-6021/911	
Corrective Action:		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 229197 Type: WELL API Number: 103-06284 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well on plunger lift

Well lacks wellbore diagram

Corrective Action: Comply with CECMC Rule 420

Date: 09/05/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						
Ditches						
		Ditches				
Berms	Fail					Tunnel erosion/Berm needs maintenance
		Berms				
Other	Fail					Failure to minimize erosion & sediment

Comment: 1. Failure to minimize erosion & transport of sediment - Erosion & transport of sediment on outslope/sediment migrating onto location/insufficient BMP's  
2. Tunnel erosion/Berm needs maintenance

Corrective Action: Comply with CECMC 1000 series rules

Date: 08/20/2025

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 07/29/2025 at approximately 11:33 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD at Location ID #314651 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Stormwater - Failure to minimize erosion &amp; transport of sediment/insufficient BMP's - Comply with CECMC 1000 series rules with a CA date of 08/20/2025</li> <li>2. Inspected Facilities - Well lacks wellbore diagram - Comply with CECMC rule 420 with a CA date of 09/5/2025</li> <li>3. Signs/Marker - Wellhead sign lacks required information - Comply with CECMC rule 605 with a CA date of 09/5/2025</li> <li>4. Signs/Marker - Battery sign contains inaccurate nearest public road information - Comply with CECMC rule 605 with a CA date of 09/5/2025</li> </ol> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	popejoyd	08/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404306071	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175367">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175367</a>
713400954	713400953 Inspection- Audit Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175361">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175361</a>