

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2025

Submitted Date:

08/12/2025

Document Number:

713400974

FIELD INSPECTION FORM

Loc ID 315247 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 734 MAIN STREET 3RD FLOOR
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Koch, Benjamin		bzkoch@blm.gov	
GAS, UTAH		inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230474	WELL	PR	07/01/2020	GW	103-08138	CHANCELLOR-FEDERAL 20-2	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign lacks required information		
Corrective Action:	Comply with CECMC rule 605		Date: 09/12/2025
Type	OTHER		
Comment:	Sign on meter house		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	970-693-6021	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230474 Type: WELL API Number: 103-08138 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
Berms						
		Compaction				Light compaction
Ditches						
		Ditches				
		Berms				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 08/6/2025 at approximately 12:45 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP CHANCELLOR-FEDERAL #20-2 PAD at Location ID #315247 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Signs/Marker - Wellhead sign lacks required information - Comply with CECMC rule 605 with a CA date of 09/12/2025</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	08/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400975	713400974 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7183731