

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404314231

Date Received:
08/12/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>ERIN JOSEPH</u>	<u>970-515-1169</u>	<u>ECMCInspections@Oxy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 717900275
Inspection Date: 07/25/2025 FIR Submit Date: 08/01/2025 FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 332541

Location Name: HSR-FROMHOLZ-63N66W Number: 2NWNW County: _____
Qtrqtr: NWN Sec: 2 Twp: 3N Range: 66W Meridian: 6
W
Latitude: 40.259620 Longitude: -104.751960

FACILITY - API Number: 05-123-00 Facility ID: 332541

Facility Name: HSR-FROMHOLZ-63N66W Number: 2NWNW
Qtrqtr: NWN Sec: 2 Twp: 3N Range: 66W Meridian: 6
W
Latitude: 40.259620 Longitude: -104.751960

CORRECTIVE ACTIONS:

1 CA# 206739

Corrective Action: Comply with Rules 606 and 1002.f.(2).D. Date: 08/15/2025

Response: CA COMPLETED Date of Completion: 08/06/2025

Operator Comment: SEE ATTACHED LOCATION PHOTOS

ECMC Decision: _____

ECMC
Representative:

2 CA# 206740

Corrective Action: Comply with Rule 902.b to install or repair wildlife protection equipment. The location will remain out of compliance until the corrective action has been resolved.

Date: 08/15/2025

Response: CA COMPLETED

Date of Completion: 08/06/2025

Operator
Comment:

SECURED PANELS AROUND THE EXCAVATION SEE ATTACHED PHOTOS

ECMC Decision:

ECMC
Representative:

3 CA# 206741

Corrective Action: Manage waste in compliance with Rule 913.b.iv and ECMC Guidance 913.b.(5)B i-v. Prior to spill/remediation closure Operator will collect soil samples from underneath the observed soil stockpile area.

Date: 08/15/2025

Response: CA COMPLETED

Date of Completion: 08/06/2025

Operator
Comment:

STOCKPILED HAVE BEEN HAULED OFF OF LOCATION, SEE ATTACHED PHOTOS

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: REGULATORY

Date: 8/12/2025 3:39:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404314231	FIR RESOLUTION SUBMITTED
404314246	LOCATION PHOTOS

Total Attach: 2 Files