

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2025

Submitted Date:

08/06/2025

Document Number:

715801313

FIELD INSPECTION FORM

Loc ID 333279 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------|---------------------------------|
| | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 240209 | WELL | SI | 09/01/2024 | OW | 123-07997 | DECHANT-STATE 3 | SI |

General Comment:

[This is a field audit of the scout card, related documents and the location](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------------------------------------------------------------|-------|------------|
| | Type WELLHEAD | | |
| Comment: | Sign not legible Sign not updated to reflect current operator | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 09/06/2025 |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|-----------------------------------------------------|-------|------------|
| Type | WEEDS | | |
| Comment: | Vegetation throughout location needs to be removed. | | |
| Corrective Action: | Comply with rule 606 | Date: | 08/13/2025 |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: Hog fence

Corrective Action: Date:

Equipment:

| | | | corrective date |
|---------------------------------------------------|--|-------|-----------------|
| Type: Pump Jack # 1 | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead # 1 | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover # 1 | | | |
| Comment: Electric motor | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment # 1 | | | |
| Comment: Electric panel, Meter box & transformers | | | |
| Corrective Action: | | Date: | |

Venting:

Yes/No NO

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 240209 Type: WELL API Number: 123-07997 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI since 8-2024

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>ECMC Inspection Report Summary On Wednesday 8-6-2025 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kuuffman Location #333279 API #05-123-07997 Well name:Dechant-State 3 County: Weld Weather: Cloudy Temp: 98* Location: dry While there, I observed a wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 605.g signs: CA date 9-6-2025 606 housekeeping: CA date 8-13-2025 Any corrective actions from previous Inspections that have not been addressed are still applicable See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> | revasr | 08/06/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 404307841 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7177163 |
| 715801314 | Location photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7177153 |