

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2025

Submitted Date:

08/13/2025

Document Number:

713400983

FIELD INSPECTION FORM

Loc ID 316069 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 734 MAIN STREET 3RD FLOOR
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
GAS, UTAH		inspections@utahgascorp.com	

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign lacks required information		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	970-693-6021/911	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Tank not equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	30 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
		Ditches				
Compaction						Light compaction
Berms						
		Compaction				Light compaction

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 08/7/2025 at approximately 14:35 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL 20-16 PAD at Location ID #316069 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.</p> <p>While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	08/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400984	713400983 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186633