

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404315606

Date Received:  
08/13/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10805  
Name of Operator: FULCRUM ENERGY OPERATING LLC  
Address: 240 SAINT PAUL STREET SUITE 502  
City: DENVER State: CO Zip: 80206

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Rikki Ross</u>	<u>970-896-5665</u>	<u>rikki.ross@fulcrumeo.com</u>
		<u>inspections@fulcrumeo.com</u>
		<u>annalee@fulcrumef.com</u>
		<u>aaron.trujillo@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 712300116  
Inspection Date: 05/07/2025 FIR Submit Date: 06/04/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC Company Number: 10805  
Address: 240 SAINT PAUL STREET SUITE 502  
City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 463987

Location Name: PRU Alcorn Number: 0880 S10 Pad County: \_\_\_\_\_  
Qtrqr: NWNE Sec: 10 Twp: 8N Range: 80W Meridian: 6  
Latitude: 40.685589 Longitude: -106.357169

FACILITY - API Number: 05-057-00 Facility ID: 463987

Facility Name: PRU Alcorn Number: 0880 S10 Pad  
Qtrqr: NWNE Sec: 10 Twp: 8N Range: 80W Meridian: 6  
Latitude: 40.685589 Longitude: -106.357169

CORRECTIVE ACTIONS:

**1** CA# 205309

Corrective Action: Comply with Rule 912.a and clean spill/impacts; comply with Rule 906.a-d for disposal of Non-E&P Waste.

Date: 07/02/2025

Response: CA COMPLETED

Date of Completion: 06/17/2025

Operator Comment: Cement has been scraped and cleaned from location. Contaminants were disposed of per regulations.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 205310

Corrective Action: Remove and properly dispose of impacted material pursuant to Rule 912.a. Clean/remediate impacts to Table 915-1 cleanup concentrations.

Date: 07/02/2025

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 08/13/2025

Operator Comment: Stained/impacted soils have been removed from location and disposed of, per regulations.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 205311

Corrective Action: Comply with Rule 606.

Date: 06/11/2025

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 06/11/2025

Operator Comment: Trash has been cleaned up and removed from location.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: \_\_\_\_\_

Title: EHS Field Advisor

Date: 8/13/2025 2:06:46 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404315606	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files