

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404316452

Date Received:
08/14/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

9 of 9 CAs from the FIR responded to on this Form

9 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100714
Inspection Date: 08/05/2025 FIR Submit Date: 08/07/2025 FIR Status: _____

Inspected Operator Information:

Company Name: QB ENERGY OPERATING LLC Company Number: 10844
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335842

Location Name: Latham Number: CD-32 596 County: _____
Qtrqtr: NWN Sec: 32 Twp: 5S Range: 96W Meridian: 6
W
Latitude: 39.576260 Longitude: -108.197481

FACILITY - API Number: 05-045-00 Facility ID: 335842

Facility Name: Latham Number: CD-32 596
Qtrqtr: NWN Sec: 32 Twp: 5S Range: 96W Meridian: 6
W
Latitude: 39.576260 Longitude: -108.197481

CORRECTIVE ACTIONS:

1 CA# 206936

Corrective Action: Comply with Rule 603.o. Maintain BMP to ensure secondary containment is sufficiently impervious to contain a spill or release. Date: 08/22/2025

Response: CA COMPLETED Date of Completion: 08/13/2025

Operator Comment: Replaced secondary tank containment panel and repaired liner to comply with ECMC rule 603.o.

ECMC Decision: _____

ECMC
Representative:

2 CA# 206937

Corrective Action:

Date: 08/14/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

3 CA# 206938

Corrective Action:

Date: 08/14/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

4 CA# 206939

Corrective Action:

Date: 08/14/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

5 CA# 206940

Corrective Action:

Date: 08/14/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

6 CA# 206941

Corrective Action:

Date: 08/14/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment: Removed all trash and unused equipment from location to comply with ECMC rule 606.

ECMC Decision: _____

ECMC Representative: _____

7 CA# 206942

Corrective Action: Maintain Fence on Location.

Date: 08/22/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment: Repaired all damaged barbed wire fencing on and around location.

ECMC Decision: _____

ECMC Representative: _____

8 CA# 206943

Corrective Action: Comply with Rule 605.g: Upon the Director's approval of a Form 9 the Buying Operator will have 60 days to replace or update all signs at the Oil and Gas Location so that the signs comply with Rule 605.

Date: 09/07/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment: Installed new signage to comply with ECMC rule 605.

ECMC Decision: _____

ECMC Representative: _____

9 CA# 206944

Corrective Action: Comply with Rule 603.j and 1003.a

Date: 09/07/2025

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator Comment: Anchor was no longer needed and was removed to comply with ECMC rules for Anchor marking requirements in both 603.j and 1003.a.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404316452	FIR RESOLUTION SUBMITTED
404316461	Solar Panel Area
404316462	Liner Repair
404316464	Liner Repair 2
404316466	Signage
404316467	Cap Installed
404316469	Tank Containment Repair
404316470	Repaired Fencing
404316476	Stormwater
404316477	Tank Cap Wildlife
404316478	Removed Anchor

Total Attach: 11 Files