

ERF → DILLON

COLORADO



99999999


ION COMMISSION
RT




NOTICE OF UNSATISFACTORY INSPECTION
 NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 087-05868-1	LEASE NAME: Ambrose 1
LOCATION: NWNW 6-2N-58	OPERATOR: Stuarco Oil Co.
DATE: 2-23-96	INSPECTOR: E. Bratley
Insp. Type: SR	Insp. Status: PA
PA: Y <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/>
Viol.: Y <input checked="" type="radio"/>	NOV: Y <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)	SCANNED	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)	 00091994	
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	grassy field	
Miscellaneous	3" riser, 1" riser, 4x4 cut pad probably old battery site.	



CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.