

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2025

Submitted Date:

08/12/2025

Document Number:

711902678

FIELD INSPECTION FORM

Loc ID: 317088 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 76830
Name of Operator: SCHMID PROPERTIES INC
Address: PO BOX 389
City: HICO State: TX Zip: 76457

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		tenniswilliam123@cs.com	
Gomez, Jason		jason.gomez@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236071	WELL	PR	06/01/2020	OW	121-08561	CLARK 8-35	PR

General Comment:

THIS IS A FOLLOW-UP FIR FROM DOC#711901265 - DATED 9/10/2024 - ANY/ALL CA DATES HAVE EXPIRED CITED WITHIN DOC# 711901265

A REVIEW OF THE ECMC WELL FILE / SCOUT CARD / FIR INSPECTIONS . . . SHOWS NO DOCUMENTATION FOR API# 121-08561 (CLARK 8-35) OR FACILITY #236071 UPDATING CURRENT STATUS OF ENVIRONMENTAL CA'S AND DATES FOR COMPLIANCE.

PLEASE SEE PHOTOGRAPHS ATTACHED TO THIS INSPECTION FOR ON-SITE CURRENT CONDITIONS AND POTENTIAL COMPLIANCE ISSUES REMAINING.

NO UPDATED CA'S AND ASSOCIATED DATES ARE OFFERED IN THIS FIR PENDING REVIEW AND FOLLOW-UP.

NOTE TO OPERATOR: CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES IMMEDIATELY

Location

Lease Road:			
Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	TANK PLACARDING NON-COMPLIANT		
Corrective Action:	COMPLY WITH RULE 605 SERIES	Date:	11/12/2025

Emergency Contact Number:			
Comment:	CALLED 337- 484-3184 AWAITING RETURN CALL @ 12:56 PM 8/12/2025 337-484 - 3650 AWAITING RETURN CALL @ 12:59 PM 8/12/2025 RECEIVED BY LIVE ATTENDANT ANSWERING SERVICE. UPDATE: RECEIVED RETURN CALL FROM MR. WILLIAM SCHMID WITHIN (30) MINUTES - SATISFACTORY EMERGENCY RESPONSE		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No		
Comment:	CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES RELATED TO REMEDIATION OF SKIM PIT AND DISPOSITION OF CONTAMINATED SOILS SKIM PIT REMAINS OPEN - UNREMIEDIATED SOIL PILE DOES NOT PROVIDE ADEQUATE MEMBRANE PROTECTION FOR CONTAMINATION MIGRATION - BERMS CONSTRUCTED FROM CONTAMINATED SOILS REMOVED FROM SKIM PIT - BERMS CONTAINMENT IS INADEQUATE		
<input type="checkbox"/>	Multiple Spills and Releases?		

Equipment:			corrective date
Type: Other	# 0		
Comment:	NO CHANGE IN EQUIPMENT INVENTORIED		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	INADEQUATE PLACARDING ON TANKS AT BATTERY				
Corrective Action:				Date:	

Paint	
Condition	
Other (Content)	
Other (Capacity)	

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: INADEQUATE BERM CONTAINMENT OF CONTAMINATED SOILS FROM SKIM PIT				
Corrective Action: _____				Date: _____

Venting:

Yes/No	NO		
Comment: _____			
Corrective Action: _____		Date: _____	

Flaring:

Type		
Comment: _____		
Corrective Action: _____		Date: _____

Inspected Facilities

Facility ID: 236071 Type: WELL API Number: 121-08561 Status: PR Insp. Status: PR

Producing Well

Comment: [OW](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: SKIM PIT REMEDIATION AND SOIL PILE REMAIN UNRESOLVED CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

ECMC Comments

Comment	User	Date
NOTE TO OPERATOR: CONTACT ECMC ENVIRONMENTAL GROUP FOR REVIEW OF COMPLIANCE ISSUES ON THIS FACILITY.	schureky	08/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404314028	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7184778
711902687	FIR PHOTOGRAPHS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7184761