

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404323242

Date Received:  
08/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10670  
Name of Operator: BISON IV OPERATING LLC  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Paul Buck	(303) 882-5868	pbuck@bisonog.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696307865  
Inspection Date: 07/28/2025 FIR Submit Date: 07/29/2025 FIR Status:

Inspected Operator Information:

Company Name: BISON IV OPERATING LLC Company Number: 10670  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 416477

Location Name: Fox Creek Number: 505-2501H County:  
Qtrqr: SESE Sec: 25 Twp: 12N Range: 63W Meridian: 6  
Latitude: 40.974731 Longitude: -104.373833

FACILITY - API Number: 05-123- -00 Facility ID: 416477

Facility Name: Fox Creek Number: 505-2501H  
Qtrqr: SESE Sec: 25 Twp: 12N Range: 63W Meridian: 6  
Latitude: 40.974731 Longitude: -104.373833

CORRECTIVE ACTIONS:

1 CA# 206529

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. Contact ECMC EPS staff. Date: 08/12/2025

Response: CA COMPLETED Date of Completion: 08/12/2025

Operator Comment: All stained soil has been removed from site and the site is in compliance with Rule 905.

ECMC Decision:

ECMC Representative: \_\_\_\_\_

**2** CA# 206530

Corrective Action: Comply with Rule 606 Date: 08/12/2025

Response: CA COMPLETED Date of Completion: 08/05/2025

Operator Comment: All unused equipment as been removed from site.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 206531

Corrective Action: Comply with Rule 1105 Date: 08/12/2025

Response: CA COMPLETED Date of Completion: 08/19/2025

Operator Comment: All unmarked risers have been marked and the site is in compliance with Rule 1105.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions associated with Document No. 696307865 have been completed. The inspector for this site extended the deadline for this FIRR until 8/22/2025 due to the high water levels on site as a result of rain. Bison was able to complete all corrective actions ahead of the extended deadline. Bison will follow-up with an email that includes photographic evidence of compliance

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Buck Signed: \_\_\_\_\_

Title: EH&S Manager Date: 8/20/2025 9:39:03 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404323242	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files