

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2025

Submitted Date:

08/18/2025

Document Number:

715801376

FIELD INSPECTION FORM

Loc ID 317651 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239692	WELL	SI	05/01/2021	GW	123-07480	SUCKLA-BROWN UNIT 1	SI

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	hidden by tall vegetation.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	Tall vegetation along access road, throughout location & around all equipment needs to be removed.		
Corrective Action:	Comply with rule 606	Date:	08/25/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	fabricated steel pipe around the ancillary equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	fabricated steel pipe on the north side.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe around the pump jack		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box & transformers		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239692 Type: WELL API Number: 123-07480 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, the well is part of a 901 Order.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 06/03/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 8-18-2025 at approximately 1600 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 317651 API # 05-123-07480 Well name: Suckla-Brown Unit 1 County: Weld Weather: Clear Temp: 92* Location: Dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 606 housekeeping: Tall vegetation needs to be removed, CA date 8-25-2025. Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404320948	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193321
715801377	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7193293