

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2025

Submitted Date:

08/20/2025

Document Number:

717701667

FIELD INSPECTION FORM

Loc ID 327685 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247229	WELL	PR	03/01/2019	GW	123-15026	OCOMA 31-17	PR

General Comment:

[This is an audit of the scout card and related documents followed by a field audit.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown Vegetation around the well needs to be removed for good housekeeping. See attached Drone Photos		
Corrective Action:	Comply with Rule 606.	Date:	08/27/2025

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Equipment	#	Corrective Action	corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 247229 Type: WELL API Number: 123-15026 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/29/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Will need updated annual BH test on file after 8/29/25

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Wednesday, August 20, 2025, at approximately 9:15 AM, Inspector Adam Burns conducted an on-site audit to the following location:</p> <p>Well: Ocoma 31-17 Operator: KP Kauffman Company Inc. API# 05-123-15026 County: Weld</p> <p>During the audit, the following possible compliance issues were identified: Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. CA date of 8/27/25 A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	08/20/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404324628	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7197721
717701668	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7197707