

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2025

Submitted Date:

08/27/2025

Document Number:

717100366

FIELD INSPECTION FORM

Loc ID 329199 Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
, Inspections		rbucogccinspectionreports@chevron.onmicrosoft.com	All Chevron Inspections
Anderson, Laurel		laurel.anderson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249195	WELL	TA	04/08/2025	GW	123-16997	UPRC 13-6J	EI
491058	SPILL OR RELEASE	AC			-	UPRC 13-06J	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 491058 and Remediation Project # 40189. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: UPRC 13-06J
Spill ID: 491058
Remediation Project #: 40189
Well API #: 05-123-16997
Reported Date of Discovery: 07/31/2025
Date of Inspection: 0825/2025
Weather: Cloudy, 66°F

Current site status:

- The excavation at the spill location has been backfilled.
- No indication of remedial activities present.
- Pieces of cement were visible in multiple areas of the location.
- Pieces of trash or E&P waste (pipe fittings) were visible in multiple areas of the location.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment: Pieces of cement and trash or E&P waste (pipe fittings) were visible in multiple areas of the location.

Corrective Action: Comply with Rule 606. Properly dispose of any E&P waste in accordance with Rule 905.

Date: 09/03/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 249195 Type: WELL API Number: 123-16997 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491058 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 40189 was created for the plugging and abandonment of the UPRC 13-06J wellhead and decommissioning of the associated flowline. Spill ID 491058 was created to address the remediation of impacts identified at the wellhead. The excavation at the spill location has been backfilled. No indication of remedial activities present. Reporting is required within 90 days of work beginning under Remediation Project # 40189.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404332747	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207230
717100367	ECMC Photo Log - UPRC 13-06J - 08.25.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207223