

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2025

Submitted Date:

09/04/2025

Document Number:

714202488

**FIELD INSPECTION FORM**

Loc ID 328520 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248291	WELL	PR	08/01/2023	OW	123-16089	WYATT 33-22	PR

**General Comment:**

[This is an inspection in response to complaint doc#: 200451511.](#)

**Inspected Facilities**

Facility ID: 248291 Type: WELL API Number: 123-16089 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Complaint**

Comment:

Inspection in response to complaint.  
 Field Inspector Assigned: Brittani Santistevan  
 Complaint Received  
 Date: 09/02/25  
 Complaint Contacted: No  
 Date: Time:  
 Location ID #: 328520  
 Inspection Document #: 714202478  
 Complaint Inspection Doc: 714202488  
 Complaint Document #: 200451511  
 Nature of Complaint: Odor  
 Field Inspector Actions:  
 On September 4, 2025, I Brittani Santistevan, area field inspector, was assigned a complaint received by ECMC staff in reference to odor. The complainant stated an odor was occurring outside of complainant's home. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did smell unusual odors in/around location. I performed a FLIR Audit on the location, you can view my findings attached to inspection DOC#: 714202478.  
 At the time of inspection, I spoke with Manny Silva via telephone, and he stated he would send some one out immediately to location to resolve the issue. The foreman that arrived to location stated he would have to get a workover rig to preform repairs on the pumpjack.  
 Weather conditions: sunny, dry ground  
 A violation of ECMC rules was observed at the time of the inspection.  
 All information reviewed and site inspection information were submitted to the ECMC for further review.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12