

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2025

Submitted Date:

09/03/2025

Document Number:

719000587

FIELD INSPECTION FORM

Loc ID 306933 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 7125
Name of Operator: BEEMAN OIL & GAS INC
Address: 13635 E 104TH AVENUE STE 400
City: COMMERCE CITY State: CO Zip: 80022

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Lawton, Lisa	(970) 846-4639	lisa@beemanoil.com	
, Kelly		kgalloway.werc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280138	WELL	SI	11/01/2023	OW	067-09070	HUBBS 1	SI

General Comment:

Inspection Report Summary
On 9/3/25 I Inspector Charles Garcia conducted an on-site follow up inspection.
Location: HUBBS #1
Operator: BEEMAN OIL & GAS LLC
API#: 067-09070
County: LaPlata

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: WEEDS ACCUMULATEING WITHIN 25FT OF ALL SURFACE EQUIPMENT SEE LOCATION PICTURES CA RESOLVED SEE LOCATION PICTURES

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Encroaching weeds/vegetation affecting berm permeability at tank battery secondary PRAIRIE DOG BURROWS INSIDE CONTAINMENT SEE LOCATION PICTURES CA ON WEEDS IN BERM RESOLVED				
Corrective Action: PRAIRIE DOG BURROWS INSIDE CONTAINMENT Maintain berms per rule 603.				Date: 12/03/2025

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 280138 Type: WELL API Number: 067-09070 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 04/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404340840	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217609
719000595	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217602