

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404356937

Date Received:
09/16/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797
Name of Operator: DESERT EAGLE OPERATING LLC
Address: 17330 PRESTON RD STE 200D-208
City: DALLAS State: TX Zip: 75252

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Butler, Brad</u>	<u>972-345-9195</u>	<u>butleroil@yahoo.com</u>
<u>Waggoner, Kyle</u>		<u>kyle.waggoner@state.co.us</u>
<u>Bulf, Cathy</u>		<u>cathybulf@gmail.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 710500528
Inspection Date: 05/27/2025 FIR Submit Date: 06/02/2025 FIR Status:

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC Company Number: 10797
Address: 17330 PRESTON RD STE 200D-208
City: DALLAS State: TX Zip: 75252

LOCATION - Location ID: 484358

Location Name: Red Rocks Number: 1-16 County:
Qtrqtr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6
Latitude: 37.464488 Longitude: -103.518825

FACILITY - API Number: 05-071-00 Facility ID: 484358

Facility Name: Red Rocks Number: 1-16
Qtrqtr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6
Latitude: 37.464488 Longitude: -103.518825

CORRECTIVE ACTIONS:

1 CA# 205230

Corrective Action: The Operator shall investigate stained soils to determine the extent, makeup, and source of oily material in accordance with Rule 912.b.

Date: 05/29/2025

Response: CA COMPLETED Date of Completion: 06/02/2025

No criteria listed in Rules 912.b.(6).B.i-iii apply. This stained soil was erroneously identified as an oil spill, it was

Operator Comment: an area of soil discolored from long ago burning by the land owner of debris and the stump. See Attached RR 1-16 Insp Photo - Charred Soil.pdf Also attached is the lab result matrix of soil sampling performed at the identified area. The increased EC levels as seen in the sample SP-01 are indicative of ash from a fire. The high EC level did not a result from DEO E&P activities. See Attached RR 1-16 Sample Breakout - Delineation Sampling - 20250828 (2).pdf and RR 1-16 Lab Report Aug 2025.pdf

ECMC Decision: _____

ECMC Representative: _____

2 CA# 205231

Corrective Action: Operator shall continue quarterly reporting in accordance with Rule 913.e

Date: 08/04/2025

Response: CA COMPLETED

Date of Completion: 09/17/2025

Operator Comment: Delineation soil samples were scheduled and results received August 25, 2025. DEO is preparing the quarterly report to include a reclamation plan.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: No criteria listed in Rules 912.b.(6).B.i-iii apply for the soil discoloration noted at Lat 37.464927; Long -103.518785. The stained soil was erroneously identified as an oil spill. The soil discoloration was created long ago from burning by the landowner of stockpiled debris. See Attached RR 1-16 Insp Photo - Charred Soil.pdf Also attached is the lab result matrix of soil sampling performed at the identified area. The increased EC levels as seen in the sample SP-01 are indicative of ash from a fire. The high EC level did not result from DEO E&P activities. See Attached RR 1-16 Sample Breakout - Delineation Sampling - 20250828 (2).pdf and RR 1-16 Lab Report Aug 2025.pdf DEO is currently developing a remediation plan for the RR 1-16 and will continue to provide quarterly reporting.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 9/16/2025 10:10:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404357048	Photos
404357049	Soil Sample Result Matrix
404357050	Lab Report

Total Attach: 3 Files