

Audit Photos

Location Name: LOCIN OIL CORPORATION, FEDERAL-67S104W/31SENW

Location ID: 324036

Date: 9/11/2025



Sep 11, 2025 at 14:17:49
+39.412043,-109.034318
Prairie Canyon 2
De Beque CO 81630
United States



Sep 11, 2025 at 14:20:27
+39.411655,-109.034444
Prairie Canyon 2
De Beque CO 81630
United States

Location Overview – Photo #00707

Location – Photo #00715

Audit Photos

Location Name: LOCIN OIL CORPORATION, FEDERAL-67S104W/31SENW

Location ID: 324036

Date: 9/11/2025



Sep 11, 2025 at 14:18:08
+39.411716,-109.034353
Prairie Canyon 2
De Beque CO 81630
United States



Sep 11, 2025 at 14:18:24
+39.411655,-109.034444
Prairie Canyon 2
De Beque CO 81630
United States

Location – Photo #00708

Location – Photo #00709

Audit Photos

Location Name: LOCIN OIL CORPORATION, FEDERAL-67S104W/31SEW

Location ID: 324036

Date: 9/11/2025



Open-Ended Line/Wildlife Entry Hazard on Tank Screen –
Photo #00713



Wildlife Entry Hazard on Tank Screen – Photo #00712

Audit Photos

Location Name: LOCIN OIL CORPORATION, FEDERAL-67S104W/31SEW

Location ID: 324036

Date: 9/11/2025



Wildlife Entry Hazard on Tank Screen – Photo #00714



Stored Supplies – Photo #00716