




99999999

F COLORADO

OIL & GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES



SUBMIT ORIGINAL AND 1 COPY

FOR OFFICE USE ONLY			
EX	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL
 GAS WELL
 COALBED METHANE
 INJECTION WELL
 OTHER

1 NAME OF OPERATOR

NOFFSINGER MFG, CO. INC.

3 ADDRESS OF OPERATOR

P.O. Box 488, 500 6th Ave.

CITY	STATE	ZIP CODE
Greeley	CO	80631

4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

SWNE Sec3, T9N, R78W

At proposed prod zone

5 FEDERAL-INDIAN OR STATE LEASE NO.

6 PERMIT NO.

API NO

05-057-0620600

Blevins B Streit Ranch

9 WELL NUMBER

13

10 FIELD OR WILDCAT

Canadian River

11 QTR. QTR. SEC., T.R. AND MERIDIAN

SWNE Sec3, T9N, R78W

12 COUNTY

Jackson

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER _____

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- REPAIRED WELL
- OTHER

**Use Form 5 - Well Completion or Recompletion Report and Log for subsequent reports of Multiple/Commingled Completions and Recompletions*

13C. NOTIFICATION OF:

- SHUT-IN, TEMPORARILY ABANDONED (DATE _____) (REQUIRED EVERY 6 MONTHS)
- PRODUCTION RESUMED (DATE _____)
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK Oct 96 # 13435

1. Pull 4 1/2" casing.
2. Put sand and LCM in bottom of hole.
3. Fill hole with cement from 150' to surface. 7" surface at 56'.
4. Cut head off 4' below GL and weld plate on with well info.
5. Rehab location.

Note- Cement used from Redi Mix truck. 30 sks.



00242101

16. I hereby certify that the foregoing is true and correct

SIGNED William J. Rippy Jr

TELEPHONE NO. 970-858-3736

NAME (PRINT) BILL RIPPY

TITLE CONTRACTOR

DATE 11/16/96

(This space for Federal or State office use)

APPROVED

TITLE _____

DATE

1/24/97

CONDITIONS OF APPROVAL, IF ANY: