

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2025

Submitted Date:

09/12/2025

Document Number:

713401065

FIELD INSPECTION FORM

Loc ID 314769 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10605
Name of Operator: APEX OIL VENTURES INC
Address: 8823 S. REDWOOD ROAD #D-1
City: WEST JORDAN State: UT Zip: 84088

Findings:

- 22 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Callister, Jan E		jec-apex@outlook.com	
Goddard, Wes		goddardwes@yahoo.com	
Koch, Benjamin		bzkoch@blm.gov	
Schroeder, Siera		siera.schroeder@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229526	WELL	PR	04/16/2007	OW	103-07182	GILLAM-TRIGOOD- GOV'T 14	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Propane tank & chemical tank lack required labeling/not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC labeling rules A. Name of Operator; B. Operator's emergency contact telephone number; C. Tank capacity; D. Tank contents; and E. NFPA label or equivalent globally harmonized label.	Date:	10/12/2025
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Some information on production tanks labels are weathered & peeling/starting to become illegible.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	435-633-5885 / 970-620-2477 / 911		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Debris on location		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	09/19/2025
Type	OTHER		
Comment:	Staining on location. At approximately 18:10 hours I spoke with Jan Callister and informed him I was issuing a 24 hour corrective action for observed compliance issue, he told me he would have the pumper take care of it in the morning.		
Corrective Action:	Remove and properly dispose of all stained materials. Additionally contact CECMC environmental protection Specialist John Heil to discuss observed compliance issues.	Date:	09/12/2025

Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment: Oil in well cellar. At approximately 18:10 hours I spoke with Jan Callister and informed him I was issuing a 24 hour corrective action for observed compliance issue, he told me he would have the pumper take care of it in the morning.				
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Submit a Form 19 if the spill/release meets the criteria outlined in Rule 912.b. If it does not meet the reporting requirements of Rule 912.b, the Operator must provide documentation of the cleanup to EPS staff, John Heil.			Date: <u>09/12/2025</u>	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:				
Type	PUMP JACK			
Comment:	Pipe rail			
Corrective Action:				Date:

Equipment:				corrective date
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Bradenhead valve is accessible/equipped with gauge			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Propane tank			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Excavator			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			

Comment:	Chemical tank	Date:	
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Dozer	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		,
Comment:	Tanks not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

Flaring:

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 229526 Type: WELL API Number: 103-07182 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Other	Fail					Failure to minimize erosion & sediment
Berms	Fail					Secondary containment berm needs maintenance
Ditches						

Comment: [1. Failure to minimize erosion & transport of sediment off location/insufficient BMP's](#)
[2. Secondary containment berm needs maintenance](#)

Corrective Action: [Comply with CECMC Stormwater rules](#)

Date: 09/27/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 09/11/2025 at approximately 14:02 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at APEX OIL VENTURES INC GILLAM-TRIGOOD-GOV'T #14 PAD at Location ID #314769 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> Spills - Oil in well cellar with a CA date of 09/12/2025 Housekeeping - Staining on location with a CA date of 09/12/2025 Stormwater - Failure to minimize erosion & transport of sediment off location/insufficient BMP's & Secondary containment berm needs maintenance with a CA date of 09/27/2025 Housekeeping - Debris on location with a CA date of 09/19/2025 Signs/Marker - Propane tank & chemical tank lack required labeling/not in compliance with CECMC rules with a CA date of 10/12/2025 <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	09/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404353166	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7231551

713401066	713401065 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7231535
-----------	-----------------------------------	---