

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696
Location ID: 335874



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area. Location is approximately 196 yards
from Middle Water Gulch.**

Section/Township/Range: 11 6S96W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696
Location ID: 335874

65° NE
Garfield County



North West corner of location.

174° S
Garfield County



North East corner of location.

Garfield County



South West corner of location.

Garfield County



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696
Location ID: 335874



Photo # 1216 Erosion & transport of sediment off location /insufficient BMP's

Photo # 1217 Erosion & transport of sediment off location /insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696
Location ID: 335874



Photo # 1218 Erosion & transport of sediment off location /insufficient BMP's



Photo # 1219 Erosion & transport of sediment off location /insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696
Location ID: 335874



Photo # 1220 Erosion & transport of sediment off location /insufficient BMP's



Photo # 1221 Failure to maintain chemical BMP/chemical tank containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill