

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404363015

Date Received:
09/22/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 95520
Name of Operator: WESCO OPERATING INC
Address: 120 S DURBIN STREET
City: CASPER State: WY Zip: 82602

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|----------------------|---------------------|------------------------------------|
| <u>Weinert, Dave</u> | <u>307-577-5329</u> | <u>davew@kirkwoodcompanies.com</u> |
| <u>Fischer, Alex</u> | | <u>alex.fischer@state.co.us</u> |

ECMC INSPECTION SUMMARY:

FIR Document Number: 694500807
Inspection Date: 09/08/2025 FIR Submit Date: 09/08/2025 FIR Status: _____

Inspected Operator Information:

Company Name: WESCO OPERATING INC Company Number: 95520
Address: 120 S DURBIN STREET
City: CASPER State: WY Zip: 82602

LOCATION - Location ID: 435765

Location Name: Trelehan Tank Battery- LOCATION Number: _____ County: _____
Qtrqtr: NWS Sec: 32 Twp: 5N Range: 95W Meridian: 6
W
Latitude: 40.337116 Longitude: -108.091378

FACILITY - API Number: 05-081-00 Facility ID: 491239

Facility Name: danforth hills field tank battery Number: _____
Qtrqtr: NWS Sec: 32 Twp: 5N Range: 95W Meridian: 6
W
Latitude: 40.337116 Longitude: -108.091378

CORRECTIVE ACTIONS:

1 CA# 207828

Corrective Action: South east corner of the secondary containment appears has eroded and requires repair. The operator shall evaluate and repair as necessary to ensure compliance with 603.e, 150% of the largest volume tank.

Date: 09/22/2025

Response: CA COMPLETED

Date of Completion: 09/10/2025

Operator Comment: Wesco staff measured the containment in question then calculated the containment volume and determined that as constructed it meets ECMC standards.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Wesco staff measured the containment in question and determined that as constructed it meets ECMC standards.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dave Weinert Signed: _____

Title: HSE Coordinator Date: 9/22/2025 5:13:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
| 404363015 | FIR RESOLUTION SUBMITTED |

Total Attach: 1 Files