

FORM  
INSPRev  
X/20

# State of Colorado

## Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2025

Submitted Date:

09/16/2025

Document Number:

714300255

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: Brown, Kari On-Site Inspection   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
 Address: 555 17TH STREET SUITE 3700  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Jacob		jevans@civiresources.com	
,		Inspections@civiresources.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
491145	SPILL OR RELEASE	CL			-	Wandell 2N67W/7NENE	EI

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 491145/Remediation Project No 40433. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Inspected Facilities**

Facility ID: 491145 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill excavation has been backfilled; no soil has been stockpiled on location. Pink flagging was present on location denoting sample locations.

Corrective Action: Operator shall provide an updated Form 27 for Remediation #40433 with a workplan and timeline for remediation of Spill ID 491145. Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404355551	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7238517">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7238517</a>
714300256	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7238513">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7238513</a>