

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404368041

Date Received:
09/25/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>QB ENERGY</u>		<u>ecmc.inspections@qb-energy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708907489
Inspection Date: 09/17/2025 FIR Submit Date: 09/20/2025 FIR Status: _____

Inspected Operator Information:

Company Name: QB ENERGY OPERATING LLC Company Number: 10844
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335778

Location Name: UNOCAL-66S96W Number: 4NESW County: _____
Qtrqtr: NESW Sec: 4 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.551580 Longitude: -108.115440

FACILITY - API Number: 05-045-00 Facility ID: 335778

Facility Name: UNOCAL-66S96W Number: 4NESW
Qtrqtr: NESW Sec: 4 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.551580 Longitude: -108.115440

CORRECTIVE ACTIONS:

1 CA# 208171

Corrective Action: Comply with CECMC Rule 603 Date: 06/26/2025

Response: CA COMPLETED Date of Completion: 09/24/2025

Operator Comment: Patched holes in secondary containment liner to comply with ECMC rule 603.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: _____

Title: Compliance

Date: 9/25/2025 1:33:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404368041	FIR RESOLUTION SUBMITTED
404368047	Liner Repair

Total Attach: 2 Files