

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404372507

Date Received:
09/29/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
5 of 5 CAs from the FIR responded to on this Form
5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 6720
Name of Operator: ROBERT L BAYLESS PRODUCER LLC
Address: 707 17TH STREET SUITE 2975
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Trujillo, Helen</u>		<u>notices@bayless-cos.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 707801742
Inspection Date: 07/16/2025 FIR Submit Date: 08/05/2025 FIR Status: _____

Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC Company Number: 6720
Address: 707 17TH STREET SUITE 2975
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312955

Location Name: COTTONWOOD GULCH FED-68N91W Number: 25SENE County: _____
Qtrqr: SENE Sec: 25 Twp: 8N Range: 91W Meridian: 6
Latitude: 40.624467 Longitude: -107.546230

FACILITY - API Number: 05-081-00 Facility ID: 312955

Facility Name: COTTONWOOD GULCH FED-68N91W Number: 25SENE
Qtrqr: SENE Sec: 25 Twp: 8N Range: 91W Meridian: 6
Latitude: 40.624467 Longitude: -107.546230

CORRECTIVE ACTIONS:

1 CA# 206839

Corrective Action: Maintain containment to ensure spill or released materials will be maintained with containment structure. Date: 09/05/2025

Response: CA COMPLETED Date of Completion: 09/29/2025

Operator Comment: Built up containment structure

ECMC Decision:

ECMC
Representative:

2 CA# 206840

Corrective Action: Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Removed debris from around vents on pressure safety devices

ECMC Decision:

ECMC
Representative:

3 CA# 206841

Corrective Action: Remove debris

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Removed debris

ECMC Decision:

ECMC
Representative:

4 CA# 206842

Corrective Action: Install caps or plugs

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Installed cap and/or plugs

ECMC Decision:

ECMC
Representative:

5 CA# 206843

Corrective Action: Remove or put into use and provide adequate secondary containments.

Date: 09/05/2025

Response: CA COMPLETED

Date of Completion: 09/29/2025

Operator Comment: Corrected secondary containments

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Robert L. Bayless, Producer LLC addresses all the compliance issues on the document number 707801742

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Trudy Cundiff

Signed: _____

Title: Regulatory Compliance

Date: 9/29/2025 3:56:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404372530	Inspection Photos
-----------	-------------------

Total Attach: 1 Files