

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404376457

Date Received:
10/01/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10646
Name of Operator: AXIS EXPLORATION LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 697602588
Inspection Date: 09/09/2025 FIR Submit Date: 09/24/2025 FIR Status: _____

Inspected Operator Information:

Company Name: AXIS EXPLORATION LLC Company Number: 10646
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 460826

Location Name: GORDON 13-19 1-A Number: _____ County: _____
Qtrqtr: NWS Sec: 19 Twp: 6S Range: 62W Meridian: 6
W
Latitude: 39.506169 Longitude: -104.384346

FACILITY - API Number: 05-039-00 Facility ID: 490326

Facility Name: GORDON 13-19 1-A Number: _____
Qtrqtr: NWS Sec: 19 Twp: 6S Range: 62W Meridian: 6
W
Latitude: 39.506169 Longitude: -104.384346

CORRECTIVE ACTIONS:

1 CA# 208322

Corrective Action: Operator shall comply with Housekeeping Rule 606. Date: 10/01/2025

Response: CA COMPLETED Date of Completion: 10/01/2025

Operator Comment: Fencing supplies have been removed in compliance with Rule 606.

ECMC Decision: _____

ECMC Representative:

2 CA# 208323

Corrective Action: Comply with Housekeeping Rule 606.

Date: 10/01/2025

Response: CA COMPLETED

Date of Completion: 10/01/2025

Operator Comment: Trash has been removed in compliance with Rule 606.

ECMC Decision:

ECMC Representative:

3 CA# 208324

Corrective Action: Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.

Date: 10/01/2025

Response: CA COMPLETED

Date of Completion: 10/01/2025

Operator Comment: Fencing has been repaired per rule 913.b(5)B.i

ECMC Decision:

ECMC Representative:

4 CA# 208325

Corrective Action: E&P Waste shall be properly stored, handled, transported, treated, recycled, or disposed per Rule 905.

Date: 10/01/2025

Response: CA COMPLETED

Date of Completion: 10/01/2025

Operator Comment: E&P Waste has been addressed in compliance with Rule 905.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed:

Title: Sr. Regulatory Analyst

Date: 10/1/2025 3:20:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404376457	FIR RESOLUTION SUBMITTED
404376475	Inspection Report Resolution

Total Attach: 2 Files