

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/07/2025  
Submitted Date:  
10/07/2025  
Document Number:  
719700176

**FIELD INSPECTION FORM**

Loc ID 310329 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292189	WELL	SI	04/01/2017	GW	123-26250	PAPPENHEIM USX AB 13-13	SI

**General Comment:**

\*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

**Location**

Overall Good:

**Signs/Marker:**

Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Prior audit:  
CORRECTIVE ACTION Item(s):  
1.) Emergency contact number at wellsite is invalid.  
Refer to Rule 605.d for guidance.  
\*Post VALID emergency contact number at wellsite.  
Comply with Rule 605.d. (30-days). CA Date: 10/24/2025.

This audit:  
\*CORRECTIVE ACTION Item(s) RESOLUTION Comment:  
FIR Resolution Form | FIRR doc. #404374237 asserts:  
1.) Valid Emergency number posted at wellsite as of 09/30/2025.  
Operator provided photo for verification. See photo(s) #1, 2.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 292189 Type: WELL API Number: 123-26250 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.  
Prod valves shut.  
Locked-Out, Tagged-Out | LOTO.  
Yellow LTSI tag posted at wellsite.  
ECMC records last prod: 03/2017.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 04/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:   
 End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
This is a WELL inspection. (AMA: Alternate Method Audit). Well(s): 1: Shut-In   SI. Battery: Inactive   Shut-down. Inactive Battery SE corner GPS coordinates: 40.570041 / -104.506598  *Follow-up to Field Audit Report doc. #719700119 dated 09/22/2025. *Follow-up to FIR Resolution Form (FIRR) doc. #404374237 dated 09/30/2025.	evinsb	10/07/2025

<p><b>CECMC Audit Report Synopsis:</b></p> <p>On TUE 10/07/2025 at approximately 09:45 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at:                  Operator Name: NOBLE ENERGY INC                  Location Name: PAPPENHEIM USX AB-67N64W/13SWSW                  Location ID: 310329                  Well Name(s) &amp; API:                  Reference:                  See "Inspected Facilities" section on page 1 of this report.                  Location County: Weld County, Colorado                  Weather: Mostly Sunny, dry.</p> <p><b>Audit observations:</b>                  Well(s): 1: Shut-In  SI.                  Battery: Inactive   Shut-down.                  Inactive Battery SE corner GPS coordinates: 40.570041 / -104.506598</p> <p>* While conducting this audit, the following prior possible compliance issues appear to be addressed:                  *CORRECTIVE ACTION Item(s) RESOLUTION Comment:                  Refer to pg 2, Signs/Marker section of this report.</p> <p>*FIR Resolution Form   FIRR doc. #404374237 asserts:                  1.) Valid Emergency number posted at wellsite as of 09/30/2025.                  Operator provided photo for verification. See photo(s) #1, 2.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	<p>evinsb</p>	<p>10/07/2025</p>
---	---------------	-------------------

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700177	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7270341">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7270341</a>