

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404383215

Date Received:  
10/08/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name     | Phone | Email                                 |
|------------------|-------|---------------------------------------|
| <u>QB ENERGY</u> |       | <u>ecmc.inspections@qb-energy.com</u> |

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708907507  
Inspection Date: 09/17/2025 FIR Submit Date: 09/22/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: QB ENERGY OPERATING LLC Company Number: 10844  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**LOCATION** - Location ID: 324198

Location Name: CHEVRON-66S96W Number: 8NENE County: \_\_\_\_\_  
Qtrqtr: NENE Sec: 8 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.544110 Longitude: -108.122000

**FACILITY** - API Number: 05-045-00 Facility ID: 324198

Facility Name: CHEVRON-66S96W Number: 8NENE  
Qtrqtr: NENE Sec: 8 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.544110 Longitude: -108.122000

**CORRECTIVE ACTIONS:**

**1** CA# 208220

Corrective Action: Comply with CECMC Rule 603 Date: 10/12/2025

Response: CA COMPLETED Date of Completion: 10/06/2025

Operator Comment: Repaired damaged areas in secondary containment liner to comply with ECMC rule 603.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 208221

Corrective Action: Comply with CECMC Rule 602

Date: 09/29/2025

Response: CA COMPLETED

Date of Completion: 10/06/2025

Operator  
Comment:

Covered open insulation holes to prevent wildlife access and comply with ECMC rule 602.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed:

Title: Compliance

Date: 10/8/2025 8:34:33 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>       |
|------------------------|--------------------------|
| 404383215              | FIR RESOLUTION SUBMITTED |
| 404383218              | Debris Removed           |
| 404383219              | Liner Repair 2           |
| 404383220              | Liner Repair             |
| 404383221              | Open Insulation          |

Total Attach: 5 Files