

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2025

Submitted Date:

10/09/2025

Document Number:

717900316

**FIELD INSPECTION FORM**

Loc ID 318924 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10583  
Name of Operator: PETRO OPERATING COMPANY LLC  
Address: 9033 E EASTER PLACE SUITE 112  
City: CENTENNIAL State: CO Zip: 80112-

**Findings:**

6 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Farkas, Joel		joelfarkas@gmail.com	
		kari.l.brown@state.co.us	
		andy.peterson@iptenergyservices.com	

**General Comment:**

This is an environmental inspection for Location ID 318924 LG Everist Pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Weeds abundant in and around open excavation.

Corrective Action: Comply with Rules 606.c. and 1003.f.

Date: 10/23/2025

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment: There have been multiple spills at this location as well as remediation projects. Spill IDs 487481 and 485556. Rem Project Nos. 35558, 33677, and 33683. This inspection was to observe a soil sample. See photos.

Multiple Spills and Releases?

**Fencing/:**

Type

Comment: There is orange construction fencing along the open excavation that is sagging in areas but is overall functional.

Corrective Action:

Date:

**Equipment:**

corrective date

Type:

#

Comment: No active equipment on site.

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 318924 CDP: \_\_\_\_\_

**Comment:** There is currently a large open excavation on site. Approximately 30ft by 40 ft by 20 feet deep. There is what appears to be exposed groundwater at the bottom of the excavation.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** Sidewalls of the open excvation appear to be collapsing inward on the eastern side. OPERator to address.

**Corrective Action:** Install BMPs in accordance with 1002.f.(2) to prevent further sidewall collapse into the open excavation. **Date:** 10/23/2025

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404386832	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7275119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7275119</a>
717900317	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7274949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7274949</a>