

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2025

Submitted Date:

10/14/2025

Document Number:

720800062

FIELD INSPECTION FORM

Loc ID 417093 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Milne, Rachel	720-370-8580	rmilne@bisonog.com	
Binschus, Chris		chris.binschus@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Buck, Paul	303-882-5868	pbuck@bisonog.com	ALL INSPECTIONS
Garza, Tarah	970-514-3581	tgarza@bisonog.com	Environmental Compliance Specialist
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459091	WELL	AL	03/04/2021	LO	123-48703	Fox Creek 33-0461B	AL

General Comment:

[This is a Compliance Field Audit of the Scout Card, Related Documents and the Location for an abandoned well on an active Location.](#)

Inspected Facilities

Facility ID: 459091 Type: WELL API Number: 123-48703 Status: AL Insp. Status: AL

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: AL - Conductor and Well Celler appear to still be present at Wellsite. Form 4 Sundry 402617966 for Abandon Permit was filed on 03.04.2021 and Approved on 03.08.2021. Indicating that operation has not been conducted. The well has not been drilled. The site will be used in the future. Field Audit demonstrates that location construction and some part of wellbore was initiated without appropriate documentation. See Attached Photos

Corrective Action: Operator is to provide a full description of activity and current status at this location. Location and APD were indicated to have been abandoned without construction or drilling (Sundry #402617966). Provide these details on a Form 4 Sundry Notice. If any casing was placed, a Form 5 Drilling Completion Report is required. Final reclamation and pad closure need to be concluded.

Date: 10/31/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>On Wednesday 10.08.2025 at approximately 11:58 AM. I, Compliance Specialist Erica Petrie, conducted a Field Audit at Highpoint Operating Corporation / BISON IV Operating LLC, Fox Creek 33-00164B at Location #417093 in Weld County, Colorado.</p> <p>While on Location; Conductor and Well Celler were found to still be present at Wellsite. Form 4 Sundry #402617966 for Abandon Permit was filed on 03.04.2021 and Approved on 03.08.2021. Indicating that operation has not been conducted. Well has not been drilled. Site will be used in the future. Field Audit demonstrates that location construction and some part of wellbore was initiated without appropriate documentation.</p> <p>Operator is to provide full description of activity and current status at this location. Location and APD were indicated to have been abandoned without construction or drilling (Sundry #402617966). Provide these details on a Form 4 Sundry Notice. If any casing was placed, a Form 5 Drilling Completion Report is required. Final reclamation and pad closure need to be concluded.</p> <p>A follow up on this Field Audit will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC Rules. This is a summary of the Audit Report.</p>	petrie	10/14/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720800063	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284740