

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/13/2025

Submitted Date:

10/13/2025

Document Number:

697011952

**FIELD INSPECTION FORM**

Loc ID 306020 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284711	WELL	SI	04/01/2025	GW	123-23862	WC LAND 28-24	SI

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds were observed around the wellhead area, see attached photo.		
Corrective Action:	Comply with Rule 606	Date:	10/31/2025
Type	TRASH		
Comment:	Pallet next to lease road, see attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	10/31/2025

Overall Good:

**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Twine fencing		
Corrective Action:		Date:	

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment:		Location #306099				
Corrective Action:					Date:	
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**

Facility ID: 284711 Type: WELL API Number: 123-23862 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/21/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Audit Report Summary</a>                      On Monday 10/13/2025 at approximately 10:10 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KMG WC Land 28-24 location #306020 in Weld County, Colorado.                      While there, I observed weeds and trash around the wellhead location and the Bradenhead reporting appeared to be delinquent. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 10/31/2025. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	petersont	10/13/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404389399	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7278557">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7278557</a>
697011953	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7278552">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7278552</a>